




Troubleshooting




The Good



The Bad





The Ugly




Spot size uniformity

Related to hydrophobic and ionic interactions between DNA suspension and surface coating. Example, salt concentration.




Black Holes and Random Background




Solutions:

- Wash slide with SDS prior to chemical blocking step.
- Add 'cold' polyA (or polyT) and/or, tRNA, calf thymus, etc.
- Use a column-based purification kit (ie: Qiagen PCR cleanup) to clean-up probe after labelling.
- Use lower laser and/or PMT settings on scanner.




Probe Drying and/or Precipitating

- Hybridization solution dried under coverslip at edges




Solutions:

- Ensure adequate humidity in hyb chamber. One can use moistened filter paper at ends of slide away from cover slip.
- Use coverslips (like LifterSlips) that are slightly raised to allow use of greater volume of hybridization solution.



Smear spots ('comets')




Possible cause

DNA spots smear across slide prior to adequate blocking of slide coating



Solution

Make first blocking treatment a vigorous wash in 0.2% SDS




Cracking and Flaking of PL Coating


- Due to old or poorly made poly-L-lysine (PL) slides





- Solution: Spot, UV-link, and hyb PL slides within 3-4 months. Test a few slides of each PL batch before investing too much time, money, and resources



Smear spots within one grid



Due to clogged/damaged pin tip



Thanks to those that have helped us

Shauna Sommerville's Lab:

- Ian Wilson
- Erico Miura
- Shu-hsing Wu

Pat Brown's Lab:

- Camilla Mei-Fang Kao

Pam Green's Lab:

- Jeff Landgraf
- Matt Larson

U of Illinois Keck Center

- Mark Band
- Jose Pardinias

